Case 1:22-cv-11674-PBS Document 83-34 Filed 03/28/25 Page 1 of 3

EXHIBIT 34

Al Larochelle 12-5-2019 Sig Sauer, Inc.

Pistol Inspection Report

The following pistol was sent to the factory from Oklahoma Highway Patrol for Evaluation for Unintentional Discharge: P320-9-OKDPS; Serial # 58C208343

The following inspections were performed:

- 1. Checked trigger Pull (5 ¾ Pounds) Meets Factory Criteria
- 2. Checked function of Safety Lever Meets Factory Criteria
- 3. Checked function of Sear Meets Factory Criteria
- 4. Checked function of trigger bar Meets Factory Criteria
- 5. Checked function of Takedown Safety Lever Meets Factory Criteria
- 6. Checked function of Striker Safety Lock Meets Factory Criteria
- 7. Checked function of Striker assembly Meets Factory Criteria
- 8. Checked Headspace Meets Factory Criteria
- 9. Checked out of Battery test Meets Factory Criteria

Test Fired 42 rounds Gold Dot LE Duty Ammunition 9mm 124+P GDHP with no malfunctions.

Pistol Meets Factory Criteria for function, fit and finish.

Inspected pistol and found that it appears a foreign object entered the holster causing the pistol to discharge. There are a lot of scratches and gouges on the right side grip module running from the trigger guard to the beaver tail. There is a scratch on top of slide. See Pictures Below





